



Service Bulletin

File in Section: -

Bulletin No.: P11324

Date: October, 2014

PRELIMINARY INFORMATION

Subject: Locking Fuel Door May Not Unlock When Activated

Models: 2014 Chevrolet Corvette

Condition/Concern

Some customers may comment that when they unlock the fuel door, it will not unlock.

Recommendation/Instructions

An updated software calibration has been released to address this condition. Reprogram the BCM (Body Control Module).

Contact Techline Customer Support Center (TCSC) at 1-800-828-6860 (English) or 1-800-503-3222 (French) for instructions to reprogram the BCM with the special VCI number provided . Use Service Programming System (SPS) with the latest calibrations available on TIS2WEB. Refer to the SPS procedures in SI.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2810215	Body Control Module Reprogramming with SPS	Use Published Labor Operation Time